

Appendix 'A'

Record of Road Traffic Accidents

		Date	Time	Direction	Notes
1	Car	7/11/16	06:00-06:30	West towards Morecambe	Fails to negotiate roundabout. Damage to chevron board only.
2	HGV	16/11/16	06:30	East towards M6	Failed to negotiate roundabout and stuck in mud. No damage to street furniture. Driver had driven the road many times.
3	Car	17/11/16	18:18	East towards M6	Two car shunt on approach to roundabout. One minor injury. No damage to street furniture. (Log: LC-20161117-1042)
4	Car	17/11/16	21:56	Unclear from Police Log	Fails to negotiate roundabout. Damage to chevron board only. (Log: LC-20161117-1336)
5	Car	18/11/16	02:20	East towards M6	Fails to negotiate roundabout. No injury or damage to street furniture. Weather poor. (Log: LC-20161118-0116)
6	Car	18/11/16	08:40	West towards Morecambe	Fails to negotiate roundabout. Damage to chevron board only.
7	Car	18/11/16	Unknown	Unclear from report	Fails to negotiate roundabout. Damage to chevron board and vegetation only.

18/11/16: Police observed in the dark three vehicles skid on the west approach towards Morecambe and 'one rightside over the kerb back onto the road'.

Note: Lane restriction to reduce speed on approach to the roundabout installed on the evening of 23 November 2016. No further incidents reported.