## Appendix A

## DfT Highway Maintenance Incentive Element 17/18

	hispections (4 Look)		226,000	•	
risk daseu inspections	Inspection Street Lighting High Risk Columns M65 (LCC Owned) Structures Post Tension Inspections (4*£50k)		30,000 196,000		
Rapid failure of surface and binder course	A59 Rose Cottage, Mellor		60,995	outside Rose cottage	Inlay
Emergency Repairs	Road	£ Cost	60.005	Location	Treatment
Emerging Pressures					
	Total		1,686,005	1	9
	C206 Grimeford Lane, Chorley		61,542	Bolton Road to Boundary	Carriageway Resurfacing
	C197 Runshaw Lane, Chorley		72,960	M6 over bridge to Dawson Lane	Surface Dressi
	A59 Main Street, Ribble Valley		108,864	Mill Lane to Endhouse Cottage	investigation Inlay
	C439 Nateby Hall lane, Wyre		53,135	Nateby Hall lane to Bells bridge lane	through site
	C226 Roach Road, South Ribble		59,854	Roach Bridge to Firwood Lane	Carriageway Resurfacing
	C250 Golden Hill Lane, South Ribble		191,776	Golden Hill Lane : School Lane To Chapel Brow	2 Layer Inlay
	C405 Pilling Lane, Wyre		135,587	38-169	Inlay
	B5377 Park Lane, Wyre		143,526	Lindel Lane to Fordstone Avenue	to be determine through site investigation
	A577 Crosshall Brow, West Lancashire		199,105	Wigan Road to Castle Lane	Carriageway Resurfacing
	A675 Bolton Road, Chorley		194,512	Bolton Road : Calf Hey Bridge To Roddlesworth Lane	to be determine through site investigation
	A 679 Westgate, Burnley			Active Way to Trafalgar St	Inlay
	C405 Pilling Road, Wyre		186,401	Road Roundabout From 169 (Bibby's Farm - Green Dick lane	Retread
Top priority Capital programme for 18/19)	Longmeanygate C250		119,069	Midge Hall Lane to Comet	Resurfacing
BCs	Road	£ Cost		Location	Treatment

Total 1,973,000