Maintenance of Highway Assets

		Maintenance of Highway Assets			
Project Name	Division	Project description	Location of Scheme	Total Cost	Quarter
Programme: A, B & C Roads Burnley Road	Rossendale East	Surfacing	Mill Street to Town Centre	£121,595 £122,409	Q2
Builley Road	11055ETIGATE LAST	Surfacing	Forecast Outturn Capital Expenditure	£122,409	QZ
			<u> </u>	·	
Programme: Urban Unclassified	December Least	Carriagoves Decurfosing	Capital Allocation	£257,134	02
Rook Hill Road Old Lane and Knowsley crescent	Rossendale East Whitworth	Carriageway Resurfacing Carriageway Resurfacing	Full Length Part Length	£56,337 £56,028	Q2 Q2
Cooper St	Rossendale East	Carriageway Resurfacing	Hammerton Street to Blackthorn Lane	£18,143	Q2
Ashworth Road	Rossendale East	Carriageway Resurfacing	Full Length	£66,889	Q2
North Street	Whitworth	Carriageway Resurfacing	Full Length	£32,981	Q2
Ullswater Way(Bottom)	Rossendale North	Carriageway Resurfacing	Part Length	£24,751	Q2
			Forecast Outturn Capital Expenditure	£255,129	
Programme: Rural Unclassified			Capital Allocation	£75,692	
Tong Lane Phase 1	Whitworth	Carriageway Resurfacing	Bent House to Slack Gate	£76,125	Q2
			Forecast Outturn Capital Expenditure	£76,125	
Drogramma, Eastways			Conital Allocation	C111 010	
Programme: Footways Bankside Lane	Rossendale East	Footways improvement	No 146 to end	£111,949 £46,893	Q3
Fernhill Crescent	Rossendale East	Footways improvement	Full Length	£34,397	Q3
Bankside Close	Rossendale East	Footways improvement	Full Length	£19,013	Q3
Salem street	Rossendale West	Footways improvement	Part Length	£9,744	Q3
			Forecast Outturn Capital Expenditure	£110,047	
Programme: Local Priorities Response	Fund		Capital Allocation	£89,600	
Bridle way	Rossendale North	Surfacing	Turn Pike to Burnley Road East	£51,765	Q1
Whitworth Rake	Whitworth	Carriageway/drainage	Waingap Crescent to track	£39,219	Q2
			Forecast Outturn Capital Expenditure	£90,984	
Programme: Lighting Column Replace	ment		Capital Allocation	£113,941	
Rossendale Column Replacements	Various as necessary	Column Replacements	Rossendale Foreseat Outture Conital Francial iture	£113,941	Q4
			Forecast Outturn Capital Expenditure	£113,941	
Programme: Flood Risk Management &	Drainage		Capital Allocation	£90,471	
Rising Bridge, Rossendale	Rossendale West	Drainage Improvement/Flood Relief	Rising Bridge, Rossendale	£45,045	Q1
Water Street, Crawshawbooth Market Street	Rossendale North Whitworth	Drainage Improvement/Flood Relief Drainage Improvement	Water Street, Crawshawbooth Whitworth	£18,018 £22,523	Q2 Q3
Dale Street, Bacup	Rossendale East	Asset Condition Survey	Dale Street, Bacup	£4,828	Q3 Q4
			Forecast Outturn Capital Expenditure	£90,414	
D.,				044.004	
Programme: Traffic Signals Manchester Road, south of Princess			Manchester Road, south of Princess	£11,094	
Street, Haslingden	Rossendale South	Site equipment refurbishments	Street, Haslingden	£11,000	Q4
			Forecast Outturn Capital Expenditure	£11,000	
Programme: Bridges					1
			Canital Allocation	£1 058 800	
	Rossendale South	Maintenance Scheme	Capital Allocation 4774b1 Irwell Vale X694 Altken St	• •	03
4774b1 Irwell Vale	Rossendale South	Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St	£353,100	Q3
	Rossendale South Rossendale South	Maintenance Scheme Maintenance Scheme	•	• •	Q3 Q3
4774b1 Irwell Vale			4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water), B6238	£353,100	
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water)	Rossendale South Rossendale East	Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water), B6238 Burnley Road East	£353,100 £131,400 £26,800	Q3 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection	Rossendale South	Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water), B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road	£353,100 £131,400	Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal	Rossendale South Rossendale East	Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water), B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton	£353,100 £131,400 £26,800	Q3 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection	Rossendale South Rossendale East Rossendale North Rossendale South	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Principal Bridge Inspection	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water), B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road	£353,100 £131,400 £26,800 £4,200 £4,200	Q3 Q4 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection	Rossendale South Rossendale East Rossendale North	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North	£353,100 £131,400 £26,800 £4,200	Q3 Q4 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge	Rossendale South Rossendale East Rossendale North Rossendale South	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Principal Bridge Inspection	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water), B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799	£353,100 £131,400 £26,800 £4,200 £4,200	Q3 Q4 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Principal Bridge Inspection Principal Bridge Inspection	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane	£353,100 £131,400 £26,800 £4,200 £4,200	Q3 Q4 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200	Q3 Q3 Q3 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane	£353,100 £131,400 £26,800 £4,200 £4,200	Q3 Q4 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200	Q3 Q3 Q3 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200	Q3 Q3 Q3 Q3 Q3
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary	Maintenance Scheme Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,800	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance	Rossendale South Rossendale North Rossendale South Rossendale East Rossendale East Rossendale North Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200	Q3 Q4 Q3 Q3 Q3 Q3 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,800	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,800 £115,600 £1,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,800 £37,600 £115,600	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,800 £115,600 £1,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £316,100	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale West Rossendale South	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £1,000 £316,100 £316,100	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale South	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £316,100 £20,600	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale West Rossendale South	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £1,000 £316,100 £316,100	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale West Rossendale West Rossendale West	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £1,000 £316,100 £316,100 £20,600 £5,000 £5,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale West Rossendale West Rossendale West	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £1,000 £316,100 £316,100 £20,600 £5,000 £5,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale West Rossendale West Rossendale West	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District Forecast Outturn Capital Expenditure	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £1,000 £316,100 £316,100 £20,600 £5,000 £5,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation Reserve Bridges Schemes 4788b1 Cowpe Road Higher	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale West Rossendale West Rossendale West Divisions as necessary Rossendale East Rossendale West Rossendale East	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Retaining Wall Programme Investigation	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District Forecast Outturn Capital Expenditure	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £115,600 £1,000 £316,100 £20,600 £5,000 £5,000 £5,000 £90,200	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation Reserve Bridges Schemes 4788b1 Cowpe Road Higher 1821b1 Holden Wood	Rossendale South Rossendale North Rossendale South Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale South Rossendale West Rossendale West Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Retaining Wall Programme Investigation Maintenance Scheme Maintenance Scheme Maintenance Scheme Maintenance Scheme Maintenance Scheme Maintenance Scheme	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District Forecast Outturn Capital Expenditure	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £316,100 £316,100 £5,000 £5,000 £5,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation Reserve Bridges Schemes 4788b1 Cowpe Road Higher 1821b1 Holden Wood Strategic Route Principal Bridge	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale West Rossendale West Rossendale West Divisions as necessary Rossendale East Rossendale West Rossendale East	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Retaining Wall Programme Investigation Maintenance Scheme Maintenance and Footway Strengthening Scheme Strategic Route Principal Bridge	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District Forecast Outturn Capital Expenditure	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £115,600 £1,000 £316,100 £20,600 £5,000 £5,000 £5,000 £90,200	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation Reserve Bridges Schemes 4788b1 Cowpe Road Higher 1821b1 Holden Wood Strategic Route Principal Bridge Inspections	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale West Rossendale West Divisions as necessary Rossendale West Rossendale West Rossendale West Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Retaining Wall Programme Investigation Maintenance Scheme Maintenance and Footway Strengthening Scheme Strategic Route Principal Bridge Inspections	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District Forecast Outturn Capital Expenditure 4788b1 Cowpe Road Higher, U7774 Cowpe Rd 1821b1 Holden Wood, B6235 Holcombe Rd Various Rossendale District	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £1,000 £316,100 £316,100 £20,600 £5,000 £5,000 £5,000 £5,000 £9,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1
4774b1 Irwell Vale 4775b1 Lumb (Edenfield) 1816b1 Whitewell Brook (Water) 1631b1 Holt Mill (Waterfoot) Principal Bridge Inspection 1654b1 New-In-Tottington Principal Bridge Inspection 4753b1 Farholme Lane Principal Bridge Inspection 1602b1 Rushbed Principal Bridge Inspection Footbridge Structural Maintenance Bridge Structural Maintenance Retaining Wall Structural Maintenance Parapet Risk Ranking and Programme Investigation 4773B1 Ogden 6351B1 Buckden Wood 1639B1 Ewood Hodge Clough Ret Wall 32386R1 Retaining Wall Programme Investigation Reserve Bridges Schemes 4788b1 Cowpe Road Higher 1821b1 Holden Wood Strategic Route Principal Bridge	Rossendale South Rossendale East Rossendale North Rossendale South Rossendale East Rossendale North Divisions as necessary Divisions as necessary Divisions as necessary Rossendale South Rossendale West Rossendale West Divisions as necessary Rossendale West Rossendale West Rossendale West Rossendale West Divisions as necessary	Maintenance Scheme Principal Bridge Inspection Footbridge Repairs/replacements which are works that are generated from members of the public complaints, and bridge inspections on the larger footbridges Structural maintenance works to bridges Structural maintenance works to retaining walls Parapet Risk Ranking and Programme Investigation Maintenance Scheme Maintenance Scheme Retaining Wall Programme Investigation Maintenance Scheme Maintenance and Footway Strengthening Scheme Strategic Route Principal Bridge	4774b1 Irwell Vale, X694 Altken St 4775b1 Lumb (Edenfield), X362 unnamed rd 1816b1 Whitewell Brook (Water),B6238 Burnley Road East 1631b1 Holt Mill (Waterfoot), A681 Bacup Road 1654b1 New-In-Tottington, A676 Bolton Road North 4753b1 Farholme Lane, U7799 Farholme Lane 1602b1 Rushbed, A682 Burnley Road Various Rossendale District Various Rossendale District Various Rossendale District 4773B1 Ogden X3477 Ogden Vale Rd 6351B1 Buckden Wood B6214 Helmshore Rd 1639B1 Ewood B6527, Blackburn Rd Hodge Clough Ret Wall, 32386R1 B6214 Helmshore Road Various Rossendale District Forecast Outturn Capital Expenditure 4788b1 Cowpe Road Higher, U7774 Cowpe Rd 1821b1 Holden Wood, B6235 Holcombe Rd	£353,100 £131,400 £26,800 £4,200 £4,200 £4,200 £4,200 £37,600 £115,600 £115,600 £1,000 £316,100 £20,600 £5,000 £5,000 £5,000 £5,000 £5,000	Q3 Q4 Q3 Q3 Q3 Q3 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q4 Q1

Appendix H 2014/15 Rossendale Capital Programme

Improving the Safety of Streets for Vulnerable People

Project Name	Division	Project description	Location of Scheme	Total Cost	Quarter
Programme: Road Safety			Capital Allocation	£39,333	
Newchurch Road (south side) Footway, Cloughfold	Rossendale North	Provide footway on section of road without footway on south side. (Householder has offered to give up some of their front garden to enable footway to be built)	Outside 459 - 469 Newchurch Road, Cloughfold	£30,870	Q4
			Forecast Outturn Capital Expenditure	£30,870	